

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Airport Road (4551993), Hengrove, Bristol, Bristol			Area: Stockwood, Hengrove & Whitchur (NP11)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
1790	HCW: Utility Cover - Sunken	Ironwork; 91; Print out of Section 81 defects - Opposite lamp 5	14/07/2014	WTT	10 Working Days	Action Required	81805
10361	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - Outside 135 to 143	18/08/2009	WTT	10 Working Days	Action Required	7284
10362	HCW: Illum	Illuminated Sign/Bollard; 98; Print out for Lighting Section - At junction salcombe road	18/08/2009	WTT	10 Working Days	Action Required	7285
15473	HCW: Cracking	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Next to lamp 27 and outside 143	20/04/2010	WTT	10 Working Days	Job 1010306-Job Closed	17567
25938	HCW: Cracking	Hot Rolled Asphalt; 96; Print out for Area Highway Officer - Between 40 and 72	24/08/2011	WTT	10 Working Days	Job 1019903-Job Closed	34374
32624	HCW: Pot Hole Large	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside 52	03/07/2012	WTT	10 Working Days	Job 1026641-Job Closed	46296
38970	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - Between lamp 13 and 14	24/05/2013	WTT	10 Working Days	Job 1034469-Job Closed	59830
38971	HCW: Pot Hole Small	Hot Rolled Asphalt; 85; For Carillion 2 Man gang to rectify defect - Opposite lamp 15	24/05/2013	WTT	10 Working Days	Job 1034468-Job Closed	59829
43907	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - Between 50 to 62	13/12/2013	WTT	10 Working Days	Action Required	71693
48418	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near opp beechmount grove	12/02/2014	WTT	10 Working Days	Job 1044225-Job Closed	74225
48419	HCW: Pot Hole Large	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near lamp 21 past salcombe rd	12/02/2014	WTT	10 Working Days	Job 1044224-Job Closed	74224
57259	HCW: Cracking	Hot Rolled Asphalt; 96; Print out for Area Highway Officer - Between lamp 21 and lamp 28	05/05/2015	WTT	10 Working Days	Action Required	94459
73772	HW: Bitmac - Pothole	Pothole in carriageway - Lagan 102330211 - Near to the bollards by the junction with Two Acre Road	24/02/2016	LH	10 Working Days	Job 341-Job Closed	Imported Defect via Connector
76087	HW: Bitmac - Pothole	Pothole in carriageway - Lagan 102340875 - Where the road turns from single lanes to dual lanes	06/04/2016	LH	10 Working Days	Job 2664-Job Closed	Imported Defect via Connector
78306	HW: Bitmac - Pothole	Take out and retar 2 potholes in road each 1.5m2 - Near lamp 42	03/05/2016	WT	10 Working Days	Job 4892-Job Closed	Imported Defect via Connector
79096	HW: Bitmac - Crazed or Frettin	Take out and retar cracks in road size 2m2 - Opposite lamp 23	17/05/2016	WT	10 Working Days	Job 5683-Job Closed	Imported Defect via Connector
79098	HW: Bitmac - Pothole	Take out and retar pothole in road size 2m2 - Between lamp 22 and 23	17/05/2016	WT	10 Working Days	Job 5685-Job Closed	Imported Defect via Connector
79100	HW: Bitmac - Crazed or Frettin	Take out and retar cracks in road. - Near Junction 2 acres road	17/05/2016	WT	10 Working Days	Job 5687-Job Closed	Imported Defect via Connector
79122	HW: Bitmac - Crazed or Frettin	Take out and retar cracks in road size 1.8m2 - Opposite junction 2 acres road	17/05/2016	WT	10 Working Days	Job 5709-Job Closed	Imported Defect via Connector
79123	HW: Bitmac - Pothole	Take out and retar pothole in road size 2.5m2 - Between lamp 14 and 15	17/05/2016	WT	10 Working Days	Job 5710-Job Closed	Imported Defect via Connector
79131	HW: Bitmac - Pothole	Take out and retar deep pothole in road size 1m2 but 100mm deep phone etm for work to be done within 2hrs - Between opposite lamp 17 and 18	17/05/2016	WT	2hr, advised by phn	Job 5718-Job Closed	Imported Defect via Connector

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Airport Road (4551993), Hengrove, Bristol, Bristol			Area: Stockwood, Hengrove & Whitchur (NP11)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
79133	HW: Bitmac - Pothole	Take out and retar pothole in road size 1m2 - Junction Salcombe road	17/05/2016	WT	10 Working Days	Job 5720-Job Closed	Imported Defect via Connector
79136	HW: Bitmac - Pothole	Take out and retar pothole in road size 1m2 - Next to lamp 21	17/05/2016	WT	10 Working Days	Job 5723-Job Closed	Imported Defect via Connector
79138	HW: Bitmac - Crazed or Frettin	Take out and retar cracks in road size 1.8m2 - Opposite between lamp 22 and 23	17/05/2016	WT	10 Working Days	Job 5725-Job Closed	Imported Defect via Connector
79140	.11 Major Cracking Or Break Up	Take out and retar all cracking on crossing size 2.2m2 - Opposite lamp 25 at crossing	17/05/2016	WT	10 Working Days	Job 5727-Job Closed	Imported Defect via Connector
79157	HW: Bitmac - Pothole	Take out and retar 2 potholes in road each size 1.2m2. - Near lamp 42 Junction Wells Road.	17/05/2016	WT	10 Working Days	Job 5744-Job Closed	Imported Defect via Connector
81695	HW: Bitmac - Pothole	Pot hole tar 0.50m2. - Outside 52	13/07/2016	STS	2hr, advised by phn	Job 8283-Job Closed	Imported Defect via Connector
81696	HW: Bitmac - Pothole	Hole in channel tar 0.20m2 - Outside 20	13/07/2016	STS	2hr, advised by phn	Job 8284-Job Closed	Imported Defect via Connector
85958	HW: Bitmac - Pothole	Take out and retar pothole in road size 1m2. - Outside 52	24/11/2016	WT	10 Working Days	Job 12547-Job Closed	Imported Defect via Connector
Asset No : 101.00	Asst / Location :	(HW: Footway Section)					
10360	HFW: Depression	Bituminous; 83; For ETM 2 Man gang to rectify defect - Outside 14	18/08/2009	WTT	10 Working Days	Job 1004589-Job Closed	7286
20096	HFW: Other	Other; 85; For Carillion 2 Man gang to rectify defect - Next to lamp 42	03/12/2010	WTT	10 Working Days	Job 1013839-Job Closed	23881
79099	HW: Bitmac - Crazed or Frettin	Take out and cracks on footway size 3m2 - Near 18	17/05/2016	WT	10 Working Days	Job 5686-Job Closed	Imported Defect via Connector
79124	HW: Bitmac - Depression	Tar in trip hazard on footway next to cover. - Opposite between lamp 15 and 16	17/05/2016	WT	10 Working Days	Job 5711-Job Closed	Imported Defect via Connector
82184	HW: Bitmac - Crazed or Frettin	Tar in by driveway 1.2m2 - Outside 20	26/07/2016	STS	10 Working Days	Job 8773-Job Closed	Imported Defect via Connector
Site: Bath Road (4540690), Brislington, Bristol, Bristol			Area: Greater Brislington (NP08)				
Asset No : 1.00	Asst / Location :	(1) From Bath Road/Keynsham roundabout to Brislington Hill junction (2) From Wick Road junction					
2882	HCW: Utility Cover-Bstl Water	Ironwork; 117; Section 81 defect on Utility Cover Bristol Water - Opposite honda garage	24/07/2014	EMO	10 Working Days	Action Required	82454
2884	HCW: Pot Hole Small	DBM; 83; For ETM 2 Man gang to rectify defect - Near Junction Flowers Hill	15/02/2013	CJC	10 Working Days	Job 1032569-Job Closed	56131
2885	HCW: Pot Hole Small	DBM; 83; For ETM 2 Man gang to rectify defect - Outside House Number 584	16/04/2015	EMO	10 Working Days	Job 1057056-Job Closed	93593
2886	HCW: Pot Hole Small	DBM; 83; For ETM 2 Man gang to rectify defect - Outside House Number 504	16/04/2015	EMO	10 Working Days	Job 1057057-Job Closed	93594
2887	HCW: Pot Hole Small	DBM; 83; For ETM 2 Man gang to rectify defect - Opposite House Number 502	16/04/2015	EMO	10 Working Days	Job 1057079-Job Closed	93616
2888	HCW: Pot Hole Small	DBM; 83; For ETM 2 Man gang to rectify defect - Outside House Number 401	16/04/2015	EMO	10 Working Days	Job 1057078-Job Closed	93615
13518	HCW: Pot Hole Small	Hot Rolled Asphalt; 85; For Carillion 2 Man gang to rectify defect - Near entrance to Park'n'Ride	30/12/2009	CJC	10 Working Days	Job 1007929-Job Closed	13351
18364	HCW: Pot Hole Small	Hot Rolled Asphalt; 85; For Carillion 2 Man gang to rectify defect - Opposite Lighting Column 125	28/06/2010	CJC	10 Working Days	Job 1011335-Job Closed	19377

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Bath Road (4540690), Brislington, Bristol, Bristol			Area: Greater Brislington (NP08)				
Asset No : 1.00	Asst / Location :	(1) From Bath Road/Keynsham roundabout to Brislington Hill junction (2) From Wick Road jun					
18365	HCW: Gully - Blocked	Ironwork; 114; Phil Davies or Steve Corney - By lamp 134 [by exit Keynsham gar	28/06/2010	CJC	10 Working Days	Job 1011334-Job Closed	19376
25876	HCW: Concrete Channel-Damaged	Channel; 85; For Carillion 2 Man gang to rectify defect - Entrance HSBC/ Carmel Centre	23/06/2011	CJC	10 Working Days	Job 1018512-Job Closed	31892
30402	HCW: Depression	DBM; 83; For ETM 2 Man gang to rectify defect - By lamp 136	06/01/2012	CJC	10 Working Days	Job 1022683-Job Closed	39620
30403	HCW: Depression	DBM; 83; For ETM 2 Man gang to rectify defect - Entrance Keynsham Garden Centre	06/01/2012	CJC	10 Working Days	Job 1022682-Job Closed	39619
30405	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - By bus stop after Long Fox Manor	06/01/2012	CJC	10 Working Days	Job 1022681-Job Closed	39618
30408	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Entrance Long Fox Manor	06/01/2012	CJC	10 Working Days	Job 1022680-Job Closed	39617
30409	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Opposite junction Ironmould Lane	06/01/2012	CJC	10 Working Days	Job 1022684-Job Closed	39621
60318	HCW: Cracking	DBM; 83; For ETM 2 Man gang to rectify defect - Opposite Shop 828 ablefit tyres	11/08/2014	EMO	10 Working Days	Job 1050020-Job Closed	83208
60321	HCW: Cracking	DBM; 83; For ETM 2 Man gang to rectify defect - At junction bonville re	11/08/2014	EMO	10 Working Days	Job 1050021-Job Closed	83209
60325	HCW: Cracking	Concrete; 83; For ETM 2 Man gang to rectify defect - Opposite Lighting Column 130	11/08/2014	EMO	10 Working Days	Job 1050016-Job Closed	83201
60326	HCW: Utility Cover - Broken	Ironwork; 91; Section 81 - Near Junction stockwood rd	11/08/2014	EMO	10 Working Days	Action Required	83206
60327	HCW: Utility Cover - Rocking	Ironwork; 91; Section 81 - Opposite Lighting Column 121	11/08/2014	EMO	10 Working Days	Action Required	83205
71689	HCW: Utility Cover - Sunken	Ironwork; 91; Print out of Section 81 defects - Outside 485	08/11/2015	WTT	10 Working Days	Action Required	102471
71690	HCW: Gully - Sunken	Ironwork; 90; Print out for Dave Nelmes - Outside 825	08/11/2015	WTT	10 Working Days	Action Required	102476
71691	HCW: Utility Cover - Sunken	Ironwork; 91; Section 81 - Outside 471	08/11/2015	WTT	10 Working Days	Action Required	102470
71692	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside able fit	08/11/2015	WTT	10 Working Days	Job 1063203-Job Closed	102473
71693	HCW: Gully - Sunken	Ironwork; 90; Print out for Dave Nelmes - Near opposite lamp 133	08/11/2015	WTT	10 Working Days	Action Required	102478
71694	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside proper job	08/11/2015	WTT	10 Working Days	Job 1063202-Job Closed	102472
71695	HCW: Util Cover Srd Defective	Ironwork; 91; Print out of Section 81 defects - Near lamp 140	08/11/2015	WTT	10 Working Days	Action Required	102477
71696	HCW: Pot Hole Large	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - At junction sandy park road	08/11/2015	WTT	10 Working Days	Job 1063201-Job Closed	102469
71697	HCW: Utility Cover - Sunken	Ironwork; 91; Print out of Section 81 defects - Near lamp 125a	08/11/2015	WTT	10 Working Days	Action Required	102475
71698	HCW: Depression	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside hsbc	08/11/2015	WTT	10 Working Days	Job 1063204-Job Closed	102474
71710	HCW: Utility Cover - Sunken	Ironwork; 91; Print out of Section 81 defects - Outside lamp 140	01/12/2015	WTT	10 Working Days	Action Required	103036

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Bath Road (4540690), Brislington, Bristol, Bristol			Area: Greater Brislington (NP08)				
Asset No : 1.00	Asst / Location :	(1) From Bath Road/Keynsham roundabout to Brislington Hill junction (2) From Wick Road jun					
71711	HCW: Gully - Sunken	Ironwork; 90; Print out for Dave Nelmes - Near opposite lamp 135	01/12/2015	WTT	10 Working Days	Action Required	103035
71712	HCW: Depression	Hot Rolled Asphalt; 115; No defects found, no action required - Outside hsb	01/12/2015	WTT	No Action Required	Action Required	103037
72387	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near lamp 131	02/12/2015	WTT	10 Working Days	Job 1063664-Amended (Historical)	103241
72388	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside burger king	02/12/2015	WTT	10 Working Days	Job 1063620-Job Closed	103239
72389	HCW: Utility Cover - Rocking	Ironwork; 91; Print out of Section 81 defects - Near lamp 126	02/12/2015	WTT	10 Working Days	Action Required	103240
72390	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near lamp 45	02/12/2015	WTT	10 Working Days	Job 1063619-Job Closed	103238
72391	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near lamp 45	04/12/2015	WTT	10 Working Days	Job 1063633-Job Closed	103346
75059	HW: Bitmac - Pothole	2 potholes in road size 1m2 - Junction sandy park Road.	18/03/2016	WT	10 Working Days	Job 1636-Job Closed	Imported Defect via Connector
75064	HW: Bitmac - Depression	Tar in depression in surrounding to cover in road size approx 1.8m2 - Near lamp 140	18/03/2016	WT	10 Working Days	Job 1641-Job Closed	Imported Defect via Connector
78289	HW: Bitmac - Pothole	Take out and retar pothole in road and in channel size 2m2 in total. - Outside ablefit	03/05/2016	WT	10 Working Days	Job 4875-Job Closed	Imported Defect via Connector
79442	HW: Bitmac - Pothole	Several potholes - public report so unmarked. Saturday work? - At jn with Sandy Park Rd opposite Arnos Manor - outbound	19/05/2016	MD	10 Working Days	Job 6029-Job Closed	Imported Defect via Connector
85133	HW: Bollard - Damaged	Concrete traffic island needs repairs. Saturday works. Temporarily close inbound lane. Traffic to use bus lane. - Outside property number 825 Lond Fox Manor	18/10/2016	ADO	10 Working Days	Job 11722-Job Closed	Imported Defect via Connector
87135	HW: Bitmac - Depression	Take out and retar depression in road size 2m2. - Opposite national tyres and autocare	16/01/2017	WT	10 Working Days	Job 13724-Contractor Completed	Imported Defect via Connector
87751	HW: Bitmac - Pothole	Potholes around utility cover please repair with tarmac - Next to lamp post 96 outside Lidl.	31/01/2017	0117	2hr, advised by phn	Job 14340-Contractor Completed	Imported Defect via Connector
88298	HW: Bitmac - Pothole	Take out and retar pothole in road size 1.2m2 - Opposite national tyres depot	16/02/2017	WT	10 Working Days	Job 14887-Work Committed	Imported Defect via Connector
88299	HW: Bitmac - Pothole	Take out and retar pothole in road size 1m2 - Near lamp 126	16/02/2017	WT	10 Working Days	Job 14888-Work Committed	Imported Defect via Connector
88300	HW: Bitmac - Pothole	Take out and retar pothole in road size 1.1m2 - Near lamp 126	16/02/2017	WT	10 Working Days	Job 14889-Work Committed	Imported Defect via Connector
Site: Callington Road (4557003), Brislington, Bristol, Bristol			Area: Greater Brislington (NP08)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
12214	HCW: ACO Channel - Damaged	Channel; 114; Phil Davies or Steve Corney - By lowest point	07/10/2009	WTT	10 Working Days	Action Required	9714
17591	HCW: Other	Hot Rolled Asphalt; 96; Print out for Area Highway Officer - Outside 20	09/07/2010	WTT	10 Working Days	Action Required	19892
44266	HCW: Pot Hole Large	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Between opposite lamp 31 and 32	14/01/2014	WTT	10 Working Days	Job 1043355-Job Closed	72770

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Callington Road (4557003), Brislington, Bristol, Bristol			Area: Greater Brislington (NP08)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
73456	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Near lamp 13	10/02/2016	WTT	10 Working Days	Job 1064937-Amended (Historical)	105512
Asset No : 101.00	Asst / Location :	(HW: Footway Section)					
12213	HFW: Kerb - Rocking	Kerb; 85; For Carillion 2 Man gang to rectify defect - At junction wootton park	07/10/2009	WTT	10 Working Days	Job 1005914-Job Closed	9716
12215	HFW: Cracking	Bituminous; 114; Phil Davies or Steve Corney - By lampost no ?	07/10/2009	WTT	10 Working Days	Action Required	9715
39878	HFW: Other	Other; 96; Print out for Area Highway Officer - Outside hospital	05/06/2013	WTT	10 Working Days	Action Required	59957
44263	HFW: Damaged	Street Name Plate; 99; ETM Street Name Plates - Entrance to bowmead	14/01/2014	WTT	30 Working Days	Action Required	72767
44264	HFW: Pot Hole Large	Bituminous; 83; For ETM 2 Man gang to rectify defect - Opposite 86	14/01/2014	WTT	10 Working Days	Job 1043352-Job Closed	72766
44265	HFW: Pot Hole Small	Bituminous; 83; For ETM 2 Man gang to rectify defect - Opposite lamp 13	14/01/2014	WTT	10 Working Days	Job 1043351-Job Closed	72765
57509	HFW: Kerb - Rocking	Kerb; 83; ETM 2 Man - Outside 73	22/05/2015	WTT	10 Working Days	Job 1058530-Job Closed	95565
Asset No : 201.00	Asst / Location :	(HW: Verge)					
50451	HV: Missing	Street Name Plate; 99; Print out for ETM - Outside whartons	09/05/2014	WTT	10 Working Days	Action Required	78567
57510	HV: Damaged	Street Name Plate; 99; Print out for ETM - Outside overton council flat	22/05/2015	WTT	10 Working Days	Action Required	95566
80688	HW: Str Name Plate -Maintenanc	As above - Junction bownmead take away redundant snp post and mount new snp CALLINGTON ROAD.	14/06/2016	WT	10 Working Days	Job 7275-Contractor Completed	Imported Defect via Connector
Site: Hengrove Way (4568951), Hartcliffe, Bristol, Bristol			Area: Filwood Knowle & Windmill Hill (NP06)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
7860	HCW: Other	Other; 115; No defects found, no action required - At hartcliffe way roundabout	02/07/2009	WTT	No Action Required	Action Required	5066
30812	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - Next to east bound carriageway	02/03/2012	WTT	10 Working Days	Job 1023866-Job Closed	41742
42391	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - At side of east bound side	30/09/2013	WTT	10 Working Days	Action Required	66680
46463	HCW: Cracking	Hot Rolled Asphalt; 83; ETM 2 Man - At junction hengrove way roundabout	30/09/2014	WTT	10 Working Days	Job 1051724-Job Closed	85745
54865	HCW: Cracking	Hot Rolled Asphalt; 97; Print out for Area Highway Technician - Between cater road and wills way shopp	10/02/2014	WTT	10 Working Days	Action Required	74066
87886	HW: Bitmac - Pothole	Take out and retar pothole in road size 1.2m2 - Near lamp 104a	03/02/2017	WT	10 Working Days	Job 14475-Contractor Completed	Imported Defect via Connector
87888	HW: Bitmac - Pothole	Take out and retar pothole in road size 1m2 - Near lamp 106	03/02/2017	WT	10 Working Days	Job 14477-Contractor Completed	Imported Defect via Connector
87892	HW: Bitmac - Pothole	Take out and retar 2 potholes in road size from 2m2 to 2.1m2 - Opposite lamp 87	03/02/2017	WT	10 Working Days	Job 14481-Contractor Completed	Imported Defect via Connector

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Hengrove Way (4568951), Hartcliffe, Bristol, Bristol			Area: Filwood Knowle & Windmill Hill (NP06)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
87893	HW: Bitmac - Pothole	Take out and retar pothle in road size 0.8m2 - Next to lamp 88	03/02/2017	WT	10 Working Days	Job 14482-Contractor Completed	Imported Defect via Connector
Asset No : 2.00	Asst / Location :	From Creswicke Road junction to Cater Road junction (HW: Carriageway Section)					
73625	HW: Bitmac - Pothole	Take out and retar pothole in road size approx 1.8m2 - Opposite lamp 44	19/02/2016	WT	10 Working Days	Job 193-Job Closed	Imported Defect via Connector
73892	HW: Bitmac - Rutting	One patch 3*0.7m - 60mm deep Other to remove heavy rutting 7*0.7m - 70mm deep Avoid new detector loops Will need some decent TM and off peak - At edge of acceleration splay near led crossing	26/02/2016	MD	10 Working Days	Job 464-Job Closed	Imported Defect via Connector
78308	HW: Bitmac - Pothole	Take out and retar pothole in road size 5m2 - Near lamp 1 at crossing	03/05/2016	WT	10 Working Days	Job 4894-Job Cancelled	Imported Defect via Connector
78511	HW: Bitmac - Pothole	Pothole in carriageway - Lagan 102345134 - On the Westebound carriageway on approach to the roundabout with Hartcliffe Way / Whitchurch Lane	04/05/2016	LH	10 Working Days	Job 5097-Job Closed	Imported Defect via Connector
84119	HW: Bitmac - Pothole	Take out and retar pothole in road size 1.5m2 - Opposite lamp 76	19/09/2016	WT	10 Working Days	Job 10709-Job Closed	Imported Defect via Connector
84186	HW: Bitmac - Pothole	Pothole Small - Two small potholes There are two but noticeable potholes one after each other as you turn from Bamfield onto Hengrove Way, travelling in the direction of Hartcliffe. They have been there several months. (Enquiry 1042) - Near to the junction with Bamfield	20/09/2016	LH	10 Working Days	Job 10776-Job Closed	Imported Defect via Connector
87423	HW: Bitmac - Pothole	Pothole Large - Large pothole, road collapsing adjacent to a drain cover Left hand side of the road, adjacent to the bus stop on Hengrove Way, (first lay-by after the roundabout on A4174, exiting in the Brislington/Wells Rd direction) Map reference 51.415476, -2.592904 There is a drain cover on the left hand side of the road. The carriageway adjacent to the drain cover is collapsing in to the drain, resulting in a pothole approx 150 mm wide, 400 mm long and and 150 mm deep. It could trap the wheel of a motorcycle or bicycle. This fault has been there for at least 2 months. (Enquiry 2833) - Near to the Hengrove Way roundabout bus stop (first lay-by after the roundabout on A4174, exiting in the Brislington/Wells Rd direction)	23/01/2017	LH	10 Working Days	Job 14012-Job Suspended	Imported Defect via Connector
Asset No : 201.00	Asst / Location :	(HW: Verge)					
86498	HW: Furn - Hand Rail Damaged	Missing barriers x8 and 1 x damaged which needs replacing (1metre high x 1.925m length) - Between footbridge and Cater Road	09/12/2016	ADO	10 Working Days	Job 13087-Job Cancelled	Imported Defect via Connector

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Hengrove Way Roundabout (4518570), Hengrove, Bristol, Bristol			Area: Filwood Knowle & Windmill Hill (NP06)				
Asset No : 101.00	Asst / Location :	(HW: Footway Section)					
27650	HFW: Cracking	Bituminous; 115; No defects found, no action required - Between downward path	01/11/2011	WTT	No Action Required	Job 1021297-Job Closed	37090
Site: Wootton Park (4554734), Knowle, Bristol, Bristol			Area: Stockwood, Hengrove & Whitchur (NP11)				
Asset No : 1.00	Asst / Location :	(HW: Carriageway Section)					
12511	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - Outside 20	23/11/2009	WTT	10 Working Days	Job 1007081-Job Closed	11984
44555	HCW: Pot Hole Small	Hot Rolled Asphalt; 83; For ETM 2 Man gang to rectify defect - At junction high park	14/01/2014	WTT	10 Working Days	Job 1043353-Job Closed	72768
79593	HW: Bitmac - Pothole	Take out and retar pothole in road size 3.2m2 - Outside 34	20/05/2016	WT	10 Working Days	Job 6180-Job Closed	Imported Defect via Connector
79594	HW: Bitmac - Pothole	Take out and retar pothole in road size 1.5m2 - Outside 36	20/05/2016	WT	10 Working Days	Job 6181-Job Closed	Imported Defect via Connector
Asset No : 101.00	Asst / Location :	(HW: Footway Section)					
33536	HFW: Missing	Street Name Plate; 99; Print out for Steve/Hadyn at Carillion - At junction callington road	11/09/2012	WTT	10 Working Days	Action Required	49688
44556	HFW: Pot Hole Large	Concrete; 83; For ETM 2 Man gang to rectify defect - Outside 21	14/01/2014	WTT	10 Working Days	Job 1043354-Job Closed	72769